



Tailings Storage Facilities Table
September, 2019

| Property / Subsidiary | MCSA Bahia Brazil | MCSA Bahia Brazil | MCSA Bahia Brazil | MCSA Bahia Brazil | NX Gold Mato Grosso Brazil | NX Gold Mato Grosso Brazil | NX Gold Mato Grosso Brazil |
|---|---|---|---|---|--|--|--|
| 1. Tailings Facility Name/Identifier | Tailings Co-Disposal | Historic Tailings Dam | South Pilar Open Pit | R22 Open Pit | Non-Inert Tailings Dam (Pond 1 - CIL Tails) | Inert Tailings Dam (Pond 2 - Flotation Tails) | Inert Tailings Dam (Pond 3 - Flotation Tails) |
| 2. Location | -09°51'19.270" / -39°51'54.399" | -09°51'04.100" / -39°49'35.700" | -09°52'28.981" / -39°52'13.796" | -09°51'10.573" / -39°52'16.730" | -14°38'26.700" / -52°29'49.000" | -14°38'20.200" / -52° 29' 55.000" | -14°38'20.200" / -52°29'55.000" |
| 3. Ownership | Subsidiary (99.6% owned by Ero) | Subsidiary (99.6% owned by Ero) | Subsidiary (99.6% owned by Ero) | Subsidiary (99.6% owned by Ero) | Subsidiary (99.6% owned by Ero) | Subsidiary (97.6% owned by Ero) | Subsidiary (97.6% owned by Ero) |
| 4. Status | Active | Rehabilitation | Active | Closed | Active | Active | Active |
| 5. Date of initial operation | January, 2015 | January, 1980 | June, 2012 | January, 2011 | April, 2012 | April, 2012 | April, 2012 |
| 6. Is the Dam currently operated or closed as per currently approved design? | Yes | Yes | Yes | Yes | Yes | Yes | Yes |
| 7. Construction method | Co-Disposal / Co-Mingled | Rockfill Dam, Single Lift | Excavated Pit | Excavated Pit | Excavated Pit (HDPE Lined) | Rockfill Dam, Single Lift (Segmented Ring Dyke) | Rockfill Dam, Single Lift (Segmented Ring Dyke) |
| 8. Current maximum height | 14.5 meters | 7.4 meters | n/a (sub-surface) | n/a (sub-surface) | n/a (sub-surface) | 16.2 metres | 13.6 meters |
| 9. Current tailings storage impoundment volume | 5,588,893 m ³ | 45,400,000 m ³ | 670,827 m ³ | 2,316,736 m ³ | 277,659 m ³ | 89,500 m ³ | 0.0 m ³ |
| 10. Planned incremental tailings storage impoundment volume over 5 years time | 2,200,000 m ³ | 0.0 m ³ | 3,280,000 m ³ | 0.0 m ³ | 16,000 m ³ | 360,000 m ³ | 360,000 m ³ |
| 11. Most recent Independent Expert Review | May, 2019 | March, 2019 | May, 2019 | n/a | March, 2019 | March, 2019 | March, 2019 |
| 12. Do you have full and complete relevant engineering records including design, construction, operation, maintenance, and/or closure? | Yes | Yes | Yes | Yes | Yes | Yes | Yes |
| 13. What is your hazard categorization of this facility, based on the consequence of failure? | Low Risk / Low Potential | Low Risk / Medium Potential | Low Risk / Low Potential | Low Risk / Low Potential | Low Risk / Medium Potential | Low Risk / Low Potential | Low Risk / Low Potential |
| 14. What guideline do you follow for the classification system? | Ordinance No. 70.389, May, 17th, 2017 from DNPM (now ANM - National Mining Agency of Brazil) | Ordinance No. 70.389, May, 17th, 2017 from DNPM (now ANM - National Mining Agency of Brazil) | Ordinance No. 70.389, May, 17th, 2017 from DNPM (now ANM - National Mining Agency of Brazil) | Ordinance No. 70.389, May, 17th, 2017 from DNPM (now ANM - National Mining Agency of Brazil) | Ordinance No. 70.389, May, 17th, 2017 from DNPM (now ANM - National Mining Agency of Brazil) | Ordinance No. 70.389, May, 17th, 2017 from DNPM (now ANM - National Mining Agency of Brazil) | Ordinance No. 70.389, May, 17th, 2017 from DNPM (now ANM - National Mining Agency of Brazil) |
| 15. Has this facility, at any point in its history, failed to be confirmed or certified as stable, or experienced notable stability concerns, as identified by an independent engineer (even if later certified as stable by the same or a different firm)? | No | No | No | No | No | No | No |
| 16. Do you have internal/in house engineering specialist oversight of this facility? Or do you have external engineering support for this purpose? | Yes, internal and external support | Yes, internal and external support | Yes, internal and external support | Yes, internal and external support | Yes, internal and external support | Yes, internal and external support | Yes, internal and external support |
| 17. Has a formal analysis of the downstream impact on communities, ecosystems and critical infrastructure in the event of catastrophic failure been undertaken and to reflect final conditions? If so, when did this assessment take place? | Yes (May 2019) | Yes (November 2017) | Sub-Surface / Not Required | Sub-Surface / Not Required | Yes (February 2019) | Yes (September 2017) | Yes (September 2017) |
| 18. Is there a) a closure plan in place for this dam, and b) does it include long term monitoring? | Yes | Yes | Yes | Yes | Yes | Yes | Yes |
| 19. Have you, or do you plan to assess your tailings facilities against the impact of more regular extreme weather events as a result of climate change, e.g. over the next two years? | Yes | Yes | No | No | Yes | Yes | Yes |
| 20. Any other relevant information and supporting documentation. Please state if you have omitted any other exposure to tailings facilities through any joint ventures you may have. | Please refer to the technical report entitled "2018 Updated Mineral Resources and Mineral Reserves Statements of Mineração Caraíba's Vale do Curaçá Mineral Assets, Curaçá Valley" for additional scientific and technical information available on the Company's website (www.ero-copper.com) and on SEDAR (www.sedar.com) | Please refer to the technical report entitled "2018 Updated Mineral Resources and Mineral Reserves Statements of Mineração Caraíba's Vale do Curaçá Mineral Assets, Curaçá Valley" for additional scientific and technical information available on the Company's website (www.ero-copper.com) and on SEDAR (www.sedar.com) | Please refer to the technical report entitled "2018 Updated Mineral Resources and Mineral Reserves Statements of Mineração Caraíba's Vale do Curaçá Mineral Assets, Curaçá Valley" for additional scientific and technical information available on the Company's website (www.ero-copper.com) and on SEDAR (www.sedar.com) | Please refer to the technical report entitled "2018 Updated Mineral Resources and Mineral Reserves Statements of Mineração Caraíba's Vale do Curaçá Mineral Assets, Curaçá Valley" for additional scientific and technical information available on the Company's website (www.ero-copper.com) and on SEDAR (www.sedar.com) | Please refer to the technical report entitled "Mineral Resource and Mineral Reserve Estimate of the NX Gold Mine, Nova Xavantina" for additional scientific and technical information available on the Company's website (www.ero-copper.com) and on SEDAR (www.sedar.com) | Please refer to the technical report entitled "Mineral Resource and Mineral Reserve Estimate of the NX Gold Mine, Nova Xavantina" for additional scientific and technical information available on the Company's website (www.ero-copper.com) and on SEDAR (www.sedar.com) | Please refer to the technical report entitled "Mineral Resource and Mineral Reserve Estimate of the NX Gold Mine, Nova Xavantina" for additional scientific and technical information available on the Company's website (www.ero-copper.com) and on SEDAR (www.sedar.com) |